

Material Safety Data Sheet

acc. to ISO/DIS 11014

Reviewed on 06/14/2013

1 Identification of substance

- · Product details
- Trade name: SILIKAL RV 368
- · Article number: RV 368
- · Application of the substance / the preparation: Reaction resin Vinyl resin
- Manufacturer/Supplier: Silikal America 609-B Fertilla Street Carrolton, GA 30117 Tel.: 770.830.1404 Fax.: 777.830.9213 info@silikalamerica.com
- · Information department: Silikal America • Emergency information: INFOTRAC 1-800-535-5053

2 Composition/Data on components

- · Chemical characterization
- · Description: Mixture of the substances listed below with nonhazardous additions.

· Dangerous	components:	
	methyl methacrylate Xi, 👸 F; R 11-37/38-43	25-50%
103-11-7	2-ethylhexyl acrylate Xi; R 37/38-43	10-25%
38668-48-3	1,1'-(p-tolylimino)dipropan-2-ol T; R 25-52/53	0.5-2.5%
	reaction product: bisphenol-A-(epichlorhydrin) epoxy resin (number average molecular weight = 700) Xi, B N; R 36/38-43-51/53	0.5-2.5%
· Additional i	nformation: For the wording of the listed risk phrases refer to section 16.	

3 Hazards identification

· Hazard description:



Xi Irritant F Highly flammable

· Information pertaining to particular dangers for man and environment:

The product has to be labelled due to the calculation procedure of the "General Classification guideline for preparations of the EU" in the latest valid version.

- R 11 Highly flammable.
- R 37/38 Irritating to respiratory system and skin.
- R 43 May cause sensitisation by skin contact.
- Contains epoxy constituents. See information supplied by the manufacturer.

Classification system:

The classification was made according to the latest editions of international substances lists, and expanded upon from company and literature data.

(Contd. on page 2)

Printing date 06/14/2013

Reviewed on 06/14/2013

Trade name: SILIKAL RV 368

· NFPA ratings (scale 0 - 4)	(Contd. of page 1)
Health = 1 Fire = 3 Reactivity = 0	
· HMIS-ratings (scale 0 - 4)	
HEALTH1Health = 1FIRE3Fire = 3REACTIVITY0	

4 First aid measures

· General information: Immediately remove any clothing soiled by the product.

- After inhalation: Supply fresh air and to be sure call for a doctor.
- After skin contact: Immediately wash with water and soap and rinse thoroughly.
- After eye contact:

Rinse opened eye for several minutes under running water. If symptoms persist, consult a doctor.

• After swallowing: Drink copious amounts of water and provide fresh air. Immediately call a doctor.

5 Fire fighting measures

· Suitable extinguishing agents:

Foam

Sand

CO2, extinguishing powder or water spray. Fight larger fire with alcohol resistant foam.

- For safety reasons unsuitable extinguishing agents: Water with full jet
- Special hazards caused by the material, its products of combustion or resulting gases: Exothermic polymerization.

In case of fire, the following can be released:

Carbon monoxide (CO)

Hydrogen chloride (HCl)

• Protective equipment: Wear self-contained respiatory protective device.

• Additional information Cool endangered receptacles with water spray.

6 Accidental release measures

· Person-related safety precautions:

Ensure adequate ventilation

Wear protective clothing.

Keep away from ignition sources

Use respiratory protective device against the effects of fumes/dust/aerosol.

• Measures for environmental protection: Do not allow to enter sewers/ surface or ground water.

Measures for cleaning/collecting:

Absorb with liquid-binding material (sand, diatomite, acid binders, universal binders, sawdust). Dispose contaminated material as waste according to item 13.

Ensure adequate ventilation.

Do not flush with water or aqueous cleansing agents

7 Handling and storage

· Handling:

• Information for safe handling: Ensure good ventilation/exhaustion at the workplace.

(Contd. on page 3)

Printing date 06/14/2013

Reviewed on 06/14/2013

Trade name: SILIKAL RV 368

 Information about protection against explosions and fires: Keep ignition sources away - Do not smoke. Protect against electrostatic charges. Furmes can combine with air to form an explosive mixture. Store get: Requirements to be met by storerooms and receptacles: Store only in the original receptacle. Store in cool, dry conditions in well sealed receptacles. Do not allow to enter severs' surface or ground water. Information about storage in one common storage facility: Not required. Purther information about storage conditions: Store receptacle in a well ventilated area. Protect from heat and direct sunlight: Maximum storage temperature: 25°C 8 Exposure controls and personal protection Additional information about design of technical systems: No further data; see item 7. Components with limit values that require monitoring at the workplace: 80-62-6 methyl methacrylate PEL 410 mg/m², 100 ppm KEL 410 mg/m², 100 ppm SEN Additional information: The lists that were valid during the creation were used as basis. Personal protective and hygienic measures: Keep away from foodstuffs. beverages and feed. Immediately remove all solied and contaminated clothing. Wash hands before breaks and at the end of work. Avaid contact with the eyes and skin. Breathing equipment: Workplace must be properly ventilated and monitored to maintain air quality below the TLV. Organic vapour respirators are required on ontined spaces. Filter AX or Organic Vapour Cartridge. Protective gloves Filter AX or Organic Vapour Cartridge. Protection of hands: Protection of hands: Protection: Waterial of gloves Buty rubber, MBR Penetration time of glove material The exact break through time has to be found out by the manufacturer of the protective gloves and has to be observed. Expression: Expression: Tube track through time has to be found out by the manufacturer		(Contd. of pag	je 2
Protect against electrostatic charges. Furnes can combine with air to form an explosive mixture. Store only in the original receptacle. Store in cool, dry conditions in well sealed receptacles: Do not allow to enter sewers/ surface or ground water. Information about storage in one common storage facility: Not required. Further information about storage conditions: Store receptacle in a well ventilated area. Protect from heat and direct sunlight. Maximum storage temperature: 25°C 8 Exposure controls and personal protection Additional information about design of technical systems: No further data; see item 7. Components with limit values that require monitoring at the workplace: 80-62-6 methyl methacrylate PEL [410 mg/m ³ , 100 ppm REL [410 mg/m ³ , 100 ppm Long-term value: 205 mg/m ³ , 50 ppm SEN Additional information: The lists that were valid during the creation were used as basis. Personal protective and hygienic measures: Keep away from foodstuffs, beverages and feed. Immediately remove all solied and contaminated clothing. Wash hands before breaks and at the end of work. Avoid contact with the eyes and skin. Breating equipment: Workplace must be properly ventilated and monitored to maintain air quality below the TLV. Organic vapour respirators are required nonly when levels meet or exceed these values. A sel contained breathing apparatus is required in confined spaces. Filter AX or Organic Vapour Catridge. Firet AX or Organic Vapour Catridge. Firet AX or Organic Vapour Catridge. Firet AV or Organic Vapour Catridge. Firet AV or Organic Vapour Catridge. Firet Ator of blows Bulyl rubber, BR Bulyl rubber,			
Funes cân combine with air to form an explosive mixture. Storage: Requirements to be met by storerooms and receptacles: Store only in the original receptacle. Control of wordfittions in well sealed receptacles. Do not allow to enter sewers/ surface or ground water. Information about storage conditions: Store receptacle in a well ventilated area. Protect from heat and direct sunlight. Additional information about design of technical systems: No further data; see item 7. Components with limit values that require monitoring at the workplace: 80-62-6 methyl methacrylate PEL 410 mg/m², 100 ppm LE 410 mg/m², 100 ppm LE 410 mg/m², 100 ppm SEN Additional information: The lists that were valid during the creation were used as basis. Personal protective equipment: General protective equipment: General protective and hygienic measures: Keep away from foodstuffs, beverages and feed. Immediately remove all solied and contaminated clothing. Wash hands before breaks and at the end of work. Avoid contact with the eyes and skin. Brathing equipment: Workplace must be properly ventilated and monitored to maintain air quality below the TLV. Organic vapour respirators are required only when levels meet or exceed these values. A sel contained breating aparatus is required in confined spaces. Filter AX or Organic Vapour Catridge. Protection of hands: Material of gloves Buty in blore, NBR Vitrile rubber, NBR Vitrile			
 Requirements to be met by storerooms and receptacles: Store only in the original receptacle. Store in cool, dry conditions in well sealed receptacles. Do not allow to enter sewers/ surface or ground water. Information about storage conditions: Store receptacle in a well ventilated area. Protect from heat and direct sunlight. Maximum storage temperature: 25°C 8 Exposure controls and personal protection Additional information about storage technical systems: No further data; see item 7. Components with limit values that require monitoring at the workplace: 80-62-6 methyl methacrylate PEL 410 mg/m², 100 ppm REL 410 mg/m², 100 ppm Stor 'ercosing'', 50 ppm SEN Additional information: The lists that were valid during the creation were used as basis. Personal protective equipment: Comportex with limit values that require do work. Avoid contact with the eyes and skin. Breathing equipment: Workplace must be properly ventilated and monitored to maintain air quality below the TLV. Organic vapour respirators are required on ywhen levels meet or exceed these values. A sel contained breathing apparatus is required in confined spaces. Filter AV or Organic Vapour Cartridge. Protection of hands: Protection: Tightly sealed goggles 			
 Requirements to be met by storerooms and receptacles: Store only in the original receptacle. Store in cool, dry conditions in well sealed receptacles. Do not allow to enter sewers/ surface or ground water. Information about storage conditions: Store receptacle in a well ventilated area. Protect from heat and direct sunlight. Maximum storage temperature: 25°C 8 Exposure controls and personal protection Additional information about storage technical systems: No further data; see item 7. Components with limit values that require monitoring at the workplace: 80-62-6 methyl methacrylate PEL 410 mg/m², 100 ppm REL 410 mg/m², 100 ppm Stor 'ercosing'', 50 ppm SEN Additional information: The lists that were valid during the creation were used as basis. Personal protective equipment: Comportex with limit values that require do work. Avoid contact with the eyes and skin. Breathing equipment: Workplace must be properly ventilated and monitored to maintain air quality below the TLV. Organic vapour respirators are required on ywhen levels meet or exceed these values. A sel contained breathing apparatus is required in confined spaces. Filter AV or Organic Vapour Cartridge. Protection of hands: Protection: Tightly sealed goggles 	· Stora	ie:	
Store in cool, dry conditions in well sealed receptacles. Do not allow to enter sewers' surface or ground water. Information about storage in one common storage facility: Not required. Further information about storage conditions: Store receptacle in a well vertilated area. Protect from heat and direct sunlight. Maximum storage temperature: 25°C 3 Exposure controls and personal protection Additional information about design of technical systems: No further data; see item 7. Components with limit values that require monitoring at the workplace: 80-62-6 methyl methacrylate PEL [410 mg/m ² , 100 ppm REL 410 mg/m ² , 100 ppm SEN Additional information: The lists that were valid during the creation were used as basis. Personal protective equipment: General protective equipment: General protective equipment: General protective equipment: General protective equipment: Breathing equipment: Workplace must be properly ventilated and monitored to maintain air quality below the TLV. Organic vapour respirators are required only when levels meet or exceed these values. A sel contained breathing apparatus is required only when levels meet or exceed these values. A sel contained breathing apparatus is required only when levels meet or exceed these values. A sel contained breathing apparatus is required only when levels meet or exceed these values. A sel contained breathing apparatus is required only when levels meet or exceed these values. A sel contained breathing apparatus is required on y when levels meet or exceed these values. A sel contained breathing apparatus is required on y when levels meet or exceed these values. A sel contained breathing apparatus is required on y when levels meet or exceed these values. A sel contained breathing apparatus is required on y when levels meet or exceed these values. A sel contained breathing apparatus is required on y when levels meet or exceed these values. A sel contained breathing apparatus is to be observed. Protection of hands: Protection famets: Protection: Core Tore Core C			
Do not allow to enter sewers' surface or ground water. Information about storage in one common storage facility: Not required. Further information about storage conditions: Store receptacle in a well ventilated area. Protect from heat and direct sunlight. Maximum storage temperature: 25°C 3 Exposure controls and personal protection Additional information about design of technical systems: No further data; see item 7. Components with limit values that require monitoring at the workplace: 80-62-6 methyl methacrylate PEL 410 mg/m ³ , 100 ppm REL 410 mg/m ³ , 100 ppm TLV Short-term value: 210 mg/m ³ , 50 ppm SEN Additional information: The lists that were valid during the creation were used as basis. Personal protective equipment: General protective and hygienic measures: Keep away from foodstuffs, beverages and feed. Immediately remove all solied and contaminated clothing. Wash hands before breaks and at the end of work. Avoid contact with the eyes and skin. Breathing equipment: Workplace must be erporely ventilated and monitored to maintain air quality below the TLV. Organic vapour respirators are required only when levels meet or exceed these values. A self contained breathing apparatus is required on confined spaces. Filter AX or Organic Vapour Cartridge. Protective gloves Sutyl rubber, BR Nithile rubber, NBR Penetration time of glove material The exact break through time has to be found out by the manufacturer of the protective gloves and has to be observed. Eye protection: Withing rubber, NBR	Store	only in the original receptacle.	
 Information about storage in one common storage facility: Not required. Further information about storage conditions: Store receptacle in a well ventilated area. Protect from heat and direct sunlight. Maximum storage temperature: 25°C 8 Exposure controls and personal protection Additional information about design of technical systems: No further data; see item 7. Components with limit values that require monitoring at the workplace: 80-62-6 methyl methacrylate PEL [410 mg/m², 100 ppm REL [410 mg/m², 100 ppm SEN Additional information: The lists that were valid during the creation were used as basis. Personal protective and hygienic measures: Keep away from foodstuffs, beverages and feed. Immediately remove all solied and contaminated clothing. Wash hands before breaks and at the end of work. Avoid contact with the eyes and skin. Breating equipment: Workplace must be properly ventilated and monitored to maintain air quality below the TLV. Organic vapour respirators are required only when levels meet or exceed these values. A sel contained breathing apparatus is required in confined spaces. Filter AX or Organic Vapour Cartridge. Protection of hands: Material of gloves Butly rubber, BR Nitrile rubber, NBR Penetration time of glove material The exact break through time has to be found out by the manufacturer of the protective gloves and has to be observed. Eye protection: Tighty sealed goggles 	Store	n cool, dry conditions in well sealed receptacles.	
 Further information about storage conditions: Store receptacle in a well ventilated area. Protect from heat and direct sunlight. Maximum storage temperature: 25°C 8 Exposure controls and personal protection Additional information about design of technical systems: No further data; see item 7. Components with limit values that require monitoring at the workplace: 80-62-6 methyl methacrylate PEL 410 mg/m³, 100 ppm REL 410 mg/m³, 100 ppm TLV Short-term value: 205 mg/m³, 50 ppm SEN Additional information: The lists that were valid during the creation were used as basis. Personal protective equipment: General protective equipment: General protective and hygienic measures: Keep away from foodstiffs, beverages and feed. Immediately remove all solied and contaminated clothing. Wash hands before breaks and at the end of work. Avoid contact with the eyes and skin. Breathing equipment: Workplace must be properly ventilated and monitored to maintain air quality below the TLV. Organic vapour respirators are required only when levels meet or exceed these values. A sel contained breating apparatus is required in confined spaces. Filter AX or Organic Vapour Cartridge. Protection of hands: Material of gloves Butyl rubber, BR Nutrie rubber, NBR Penetration time of glove material The exact break through time has to be found out by the manufacturer of the protective gloves and has to be observed. Eye protection: Tightly sealed goggles 			
Protect from heat and direct sunlight. • Maximum storage temperature: 25°C 8 Exposure controls and personal protection • Additional information about design of technical systems: No further data; see item 7. • Components with limit values that require monitoring at the workplace: 80-62-6 methyl methacrylate PEL 410 mg/m ² , 100 ppm REL 410 mg/m ² , 100 ppm Long-term value: 205 mg/m ² , 100 ppm Long-term value: 205 mg/m ² , 100 ppm SEN • Additional information: The lists that were valid during the creation were used as basis. • Personal protective equipment: General protective equipment: General protective and hygienic measures: Keep away from foodstuffs, beverages and feed. Immediately remove all solied and contaminated clothing. Wash hands before breaks and at the end of work. Avoid contact with the eyes and skin. • Breathing equipment: Workplace must be properly ventilated and monitored to maintain air quality below the TLV. Organic vapour respirators are required only when levels meet or exceed these values. A sel contained breathing apparatus is required in confined spaces. Filter AX or Organic Vapour Cartridge. • Protection of hands: • Protection of bands: • Penetration time of gloves Butyl rubber, BR Virile rubber, BR Virile rubber, BR • Nirile rubber, BR • Nirile rubber, BR • Nirile rubber, BR • Nirile rubber, BR • Denetration time of glove material The exact break through time has to be found out by the manufacturer of the protective gloves and has to be observed. • Eye protection: • Tightly sealed goggles			
 Maximum storage temperature: 25°C 8 Exposure controls and personal protection Additional information about design of technical systems: No further data; see item 7. Components with limit values that require monitoring at the workplace: 80-62-6 methyl methacrylate PEL 410 mg/m³, 100 ppm REL 410 mg/m³, 100 ppm TLV Short-lerm value: 205 mg/m³, 50 ppm SEN Additional information: The lists that were valid during the creation were used as basis. Personal protective equipment: General protective and hygienic measures: Keep away from foodstuffs, beverages and feed. Immediately remove all solied and contaminated clothing. Wash hands before breaks and at the end of work. Avoid contact with the eyes and skin. Breathing equipment: Workplace must be properly ventilated and monitored to maintain air quality below the TLV. Organic vapour respirators are required only when levels meet or exceed these values. A set contained breathing apparatus is required in confined spaces. Filter AX or Organic Vapour Cartridge. Protective gloves Material of gloves Buty rubber, BR Nitrie rubber, NBR Penetration time of glove material The exact break through time has to be found out by the manufacturer of the protective gloves and has to be observed. Eye protection: Vightly sealed goggles 			
8 Exposure controls and personal protection • Additional information about design of technical systems: No further data; see item 7. • Components with limit values that require monitoring at the workplace: 80-62-6 methyl methacrylate PEL 410 mg/m ³ , 100 ppm REL 410 mg/m ³ , 100 ppm TLV Short-term value: 205 mg/m ³ , 50 ppm SEN • Additional information: The lists that were valid during the creation were used as basis. • Personal protective equipment: • General protective and hygienic measures: Keep away from foodstliffs, beverages and feed. Immediately remove all soiled and contaminated clothing. Wash hands before breaks and at the end of work. Avoid contact with the eyes and skin. Breathing equipment: Workplace must be properly ventilated and monitored to maintain air quality below the TLV. Organic vapour respirators are required only when levels meet or exceed these values. A set contained breathing apparatus is required in confined spaces. Filter AX or Organic Vapour Cartridge. Protection of hands: Image: Protection of gloves Buty rubber, BR Nitrile rubber, NBR Penetration time of glove material The exact break through time has to be found out by the manufacturer of the protective gloves and has to be observed.			
Additional information about design of technical systems: No further data; see item 7. Components with limit values that require monitoring at the workplace: 80-62-6 methyl methacrylate PEL 410 mg/m³, 100 ppm REL 410 mg/m³, 100 ppm Long-term value: 410 mg/m³, 100 ppm Long-term value: 205 mg/m³, 50 ppm SEN Additional information: The lists that were valid during the creation were used as basis. Personal protective equipment: General protective and hygienic measures: Keep away from foodstuffs, beverages and feed. Immediately remove all solied and contaminated clothing. Wash hands before breaks and at the end of work. Avoid contact with the eyes and skin. Breathing equipment: Workplace must be properly ventilated and monitored to maintain air quality below the TLV. Organic vapour respirators are required only when levels meet or exceed these values. A sel contained breathing aparatus is required only when levels meet or exceed these values. A sel contained breathing aparatus is required in confined spaces. Filter AX or Organic Vapour Cartridge. Protection of hands: Protection of hands: Protection of plove material The exact break through time has to be found out by the manufacturer of the protective gloves and has to be observed. Eye protection: Vightly sealed goggles	WIAXI		
Components with limit values that require monitoring at the workplace: 80-62-6 methyl methacrylate PEL 410 mg/m³, 100 ppm REL 410 mg/m³, 100 ppm TLV Short-term value: 410 mg/m³, 100 ppm Long-term value: 205 mg/m³, 50 ppm SEN Additional information: The lists that were valid during the creation were used as basis. Personal protective equipment: General protective and hygienic measures: Keep away from foodstuffs, beverages and feed. Immediately remove all soiled and contaminated clothing. Wash hands before breaks and at the end of work. Avoid contact with the eyes and skin. Breathing equipment: Workplace must be properly ventilated and monitored to maintain air quality below the TLV. Organic vapour respirators are required only when levels meet or exceed these values. A sel contained breathing apparatus is required in confined spaces. Filter AX or Organic Vapour Cartridge. Protection of hands: Protection of hands: Protective gloves Material of gloves Butyl rubber, BR Nitrile rubber, NBR Penetration time of glove material The exact break through time has to be found out by the manufacturer of the protective gloves and has to be observed. Eye protection: Vightly sealed goggles	8 Exp	sure controls and personal protection	
80-62-6 methyl methacrylate PEL 410 mg/m³, 100 ppm REL 410 mg/m³, 100 ppm TLV Short-terr value: 410 mg/m³, 100 ppm Long-term value: 205 mg/m³, 50 ppm SEN • Additional information: The lists that were valid during the creation were used as basis. • Personal protective equipment: General protective and hygienic measures: Keep away from foodstuffs, beverages and feed. Immediately remove all solied and contaminated clothing. Wash hands before breaks and at the end of work. Avoid contact with the eyes and skin. Breathing equipment: Workplace must be properly ventilated and monitored to maintain air quality below the TLV. Organic vapour respirators are required only when levels meet or exceed these values. A sel contained breathing apparatus is required in confined spaces. Filter AX or Organic Vapour Catridge. Protection of hands: Image: Protective gloves Multiple rubber, BR Nutrile rubber, NBR Penetration time of glove material The exact break through time has to be found out by the manufacturer of the protective gloves and has to be observed. Eye protection: Tightly sealed goggles			
PEL 410 mg/m³, 100 ppm REL 410 mg/m³, 100 ppm TLV Short-term value: 410 mg/m³, 100 ppm Long-term value: 205 mg/m³, 50 ppm SEN • Additional information: The lists that were valid during the creation were used as basis. • Personal protective equipment: • General protective and hygienic measures: Keep away from foodstuffs, beverages and feed. Immediately remove all soiled and contaminated clothing. Wash hands before breaks and at the end of work. Avoid contact with the eyes and skin. Breathing equipment: Workplace must be properly ventilated and monitored to maintain air quality below the TLV. Organic vapour respirators are required only when levels meet or exceed these values. A sel contained breathing apparatus is required in confined spaces. Filter AX or Organic Vapour Cartridge. Protection of hands: Image: Protective gloves Buty! rubber, BR Nitrile rubber, NBR Penetration time of glove material The exact break through time has to be found out by the manufacturer of the protective gloves and has to be observed. Eye protection: Tightly sealed goggles		· · ·	
REL 410 mg/m³, 100 ppm TLV Short-term value: 410 mg/m³, 100 ppm Long-term value: 205 mg/m³, 50 ppm SEN • Additional information: The lists that were valid during the creation were used as basis. • Personal protective equipment: • General protective and hygienic measures: Keep away from foodstuffs, beverages and feed. Immediately remove all solled and contaminated clothing. Wash hands before breaks and at the end of work. Avoid contact with the eyes and skin. Breathing equipment: Workplace must be properly ventilated and monitored to maintain air quality below the TLV. Organic vapour respirators are required only when levels meet or exceed these values. A sel contained breathing apparatus is required in confined spaces. Filter AX or Organic Vapour Cartridge. Protection of hands: Image: Protective gloves Butyl rubber, BR Nitrile rubber, NBR Penetration time of glove material The exact break through time has to be found out by the manufacturer of the protective gloves and has to be observed. Eye protection: Image: Tege protection:		· · · · ·	
TLV Short-term value: 410 mg/m³, 100 ppm Long-term value: 205 mg/m³, 50 ppm SEN • Additional information: The lists that were valid during the creation were used as basis. • Personal protective equipment: • General protective and hygienic measures: Keep away from foodstuffs, beverages and feed. Immediately remove all soiled and contaminated clothing. Wash hands before breaks and at the end of work. Avoid contact with the eyes and skin. • Breathing equipment: Workplace must be properly ventilated and monitored to maintain air quality below the TLV. Organic vapour respirators are required only when levels meet or exceed these values. A sel contained breathing apparatus is required in confined spaces. Filter AX or Organic Vapour Cartridge. • Protection of hands: • Organic of gloves Butyl rubber, BR Nitrile rubber, NBR • Penetration time of glove material The exact break through time has to be found out by the manufacturer of the protective gloves and has to be observed. • Eye protection: • Tightly sealed goggles			
Long-term value: 205 mg/m³, 50 ppm SEN • Additional information: The lists that were valid during the creation were used as basis. • Personal protective equipment: • General protective and hygienic measures: Keep away from foodstuffs, beverages and feed. Immediately remove all solied and contaminated clothing. Wash hands before breaks and at the end of work. Avoid contact with the eyes and skin. • Breathing equipment: Workplace must be properly ventilated and monitored to maintain air quality below the TLV. Organic vapour respirators are required only when levels meet or exceed these values. A self contained breathing apparatus is required in confined spaces. Filter AX or Organic Vapour Cartridge. • Protection of hands: • Material of gloves Butyl rubber, BR Nitrile rubber, NBR • Penetration time of glove material The exact break through time has to be found out by the manufacturer of the protective gloves and has to be observed. • Eye protection: • Tightly sealed goggles			
SEN • Additional information: The lists that were valid during the creation were used as basis. • Personal protective equipment: • General protective and hygienic measures: Keep away from foodstuffs, beverages and feed. Immediately remove all solide and contaminated clothing. Wash hands before breaks and at the end of work. Avoid contact with the eyes and skin. • Breathing equipment: Workplace must be properly ventilated and monitored to maintain air quality below the TLV. Organic vapour respirators are required only when levels meet or exceed these values. A sel contained breathing apparatus is required in confined spaces. Filter AX or Organic Vapour Cartridge. • Protection of hands: • Ordection of hands: • Protective gloves • Material of gloves Butyl rubber, BR Nitrile rubber, NBR • Penetration time of glove material The exact break through time has to be found out by the manufacturer of the protective gloves and has to be observed. • Eye protection: • Tightly sealed goggles			
 Personal protective equipment: General protective and hygienic measures: Keep away from foodstuffs, beverages and feed. Immediately remove all soiled and contarninated clothing. Wash hands before breaks and at the end of work. Avoid contact with the eyes and skin. Breathing equipment: Workplace must be properly ventilated and monitored to maintain air quality below the TLV. Organic vapour respirators are required only when levels meet or exceed these values. A sel contained breathing apparatus is required in confined spaces. Filter AX or Organic Vapour Cartridge. Protection of hands: Material of gloves Butyl rubber, BR Nitrile rubber, NBR Penetration time of glove material The exact break through time has to be found out by the manufacturer of the protective gloves and has to be observed. Eye protection: Tightly sealed goggles 			
 General protective and hygienic measures: Keep away from foodstuffs, beverages and feed. Immediately remove all soiled and contaminated clothing. Wash hands before breaks and at the end of work. Avoid contact with the eyes and skin. Breathing equipment: Workplace must be properly ventilated and monitored to maintain air quality below the TLV. Organic vapour respirators are required only when levels meet or exceed these values. A sel contained breathing apparatus is required in confined spaces. Filter AX or Organic Vapour Cartridge. Protection of hands: Material of gloves Butyl rubber, BR Nitrile rubber, NBR Penetration time of glove material The exact break through time has to be found out by the manufacturer of the protective gloves and has to be observed. Eye protection: Tightly sealed goggles 	Addit	onal information: The lists that were valid during the creation were used as basis.	
 General protective and hygienic measures: Keep away from foodstuffs, beverages and feed. Immediately remove all soiled and contaminated clothing. Wash hands before breaks and at the end of work. Avoid contact with the eyes and skin. Breathing equipment: Workplace must be properly ventilated and monitored to maintain air quality below the TLV. Organic vapour respirators are required only when levels meet or exceed these values. A sel contained breathing apparatus is required in confined spaces. Filter AX or Organic Vapour Cartridge. Protection of hands: Material of gloves Butyl rubber, BR Nitrile rubber, NBR Penetration time of glove material The exact break through time has to be found out by the manufacturer of the protective gloves and has to be observed. Eye protection: Tightly sealed goggles 	· Perso	nal protective equipment:	
Immediately remove all soiled and contaminated clothing. Wash hands before breaks and at the end of work. Avoid contact with the eyes and skin. Breathing equipment: Workplace must be properly ventilated and monitored to maintain air quality below the TLV. Organic vapour respirators are required only when levels meet or exceed these values. A sel contained breathing apparatus is required in confined spaces. Filter AX or Organic Vapour Cartridge. Protection of hands: Protective gloves Material of gloves Butyl rubber, BR Nitrile rubber, NBR Penetration time of glove material The exact break through time has to be found out by the manufacturer of the protective gloves and has to be observed. Eye protection: Tightly sealed goggles			
 Wash hands before breaks and at the end of work. Avoid contact with the eyes and skin. Breathing equipment: Workplace must be properly ventilated and monitored to maintain air quality below the TLV. Organic vapour respirators are required only when levels meet or exceed these values. A sel contained breathing apparatus is required in confined spaces. Filter AX or Organic Vapour Cartridge. Protection of hands: Material of gloves Butyl rubber, BR Nitrile rubber, NBR Penetration time of glove material The exact break through time has to be found out by the manufacturer of the protective gloves and has to be observed. Eye protection: Tightly sealed goggles 			
 Avoid contact with the eyes and skin. Breathing equipment: Workplace must be properly ventilated and monitored to maintain air quality below the TLV. Organic vapour respirators are required only when levels meet or exceed these values. A sel contained breathing apparatus is required in confined spaces. Filter AX or Organic Vapour Cartridge. Protection of hands: Protective gloves Material of gloves Butyl rubber, BR Nitrile rubber, NBR Penetration time of glove material The exact break through time has to be found out by the manufacturer of the protective gloves and has to be observed. Eye protection: Tightly sealed goggles 			
 Breathing equipment: Workplace must be properly ventilated and monitored to maintain air quality below the TLV. Organic vapour respirators are required only when levels meet or exceed these values. A sel contained breathing apparatus is required in confined spaces. Filter AX or Organic Vapour Cartridge. Protection of hands: Material of gloves Butyl rubber, BR Nitrile rubber, NBR Penetration time of glove material The exact break through time has to be found out by the manufacturer of the protective gloves and has to be observed. Eye protection: Tightly sealed goggles 			
Organic vapour respirators are required only when levels meet or exceed these values. A set contained breathing apparatus is required in confined spaces. Filter AX or Organic Vapour Cartridge. Protection of hands: Protection of hands: Material of gloves Butyl rubber, BR Nitrile rubber, NBR Penetration time of glove material The exact break through time has to be found out by the manufacturer of the protective gloves and has to be observed. Eye protection: Tightly sealed goggles			
 contained breathing apparatus is required in confined spaces. Filter AX or Organic Vapour Cartridge. Protection of hands: Protective gloves Material of gloves Butyl rubber, BR Nitrile rubber, NBR Penetration time of glove material The exact break through time has to be found out by the manufacturer of the protective gloves and has to be observed. Eye protection: Tightly sealed goggles 	Work	lace must be properly ventilated and monitored to maintain air quality below the TLV.	I
Filter AX or Organic Vapour Cartridge. Protection of hands:			se
 Protection of hands: Protective gloves Material of gloves Butyl rubber, BR Nitrile rubber, NBR Penetration time of glove material The exact break through time has to be found out by the manufacturer of the protective gloves and has to be observed. Eye protection: Tightly sealed goggles 			
 Material of gloves Butyl rubber, BR Nitrile rubber, NBR Penetration time of glove material The exact break through time has to be found out by the manufacturer of the protective gloves and has to be observed. Eye protection: Tightly sealed goggles 	· Prote	tion of hands:	
 Material of gloves Butyl rubber, BR Nitrile rubber, NBR Penetration time of glove material The exact break through time has to be found out by the manufacturer of the protective gloves and has to be observed. Eye protection: Tightly sealed goggles 	pul.	Protective gloves	
 Butyl rubber, BR Nitrile rubber, NBR Penetration time of glove material The exact break through time has to be found out by the manufacturer of the protective gloves and has to be observed. Eye protection: Tightly sealed goggles 			
 Butyl rubber, BR Nitrile rubber, NBR Penetration time of glove material The exact break through time has to be found out by the manufacturer of the protective gloves and has to be observed. Eye protection: Tightly sealed goggles 	·Mate	al of gloves	
 Penetration time of glove material The exact break through time has to be found out by the manufacturer of the protective gloves and has to be observed. Eye protection: Tightly sealed goggles 	Butyl	ubber, BR	
The exact break through time has to be found out by the manufacturer of the protective gloves and has to be observed. • Eye protection: Tightly sealed goggles			
has to be observed. Eye protection: Tightly sealed goggles			an
• Eye protection: Tightly sealed goggles			2110
	6	Tightly sealed goggles	
(Contd. on page 4			

Printing date 06/14/2013

Reviewed on 06/14/2013

Trade name: SILIKAL RV 368

· Body protection: Protective work clothing

(Contd. of page 3)

· General Information	
Form:	Fluid
Color:	Light yellow
	Cloudy
Odor:	Unpleasant
	Ester-like
 Change in condition 	
Melting point/Melting range:	Undetermined.
Boiling point/Boiling range:	100°C (212°F)
· Flash point:	10°C (50°F)
· Ignition temperature:	245°C (473°F)
· Auto igniting:	Product is not selfigniting.
· Danger of explosion:	Product is not explosive. However, formation of explosive air, vapor mixtures are possible.
· Explosion limits:	
Lower:	0.8 Vol %
Upper:	12.5 Vol %
· Vapor pressure at 20°C (68°F):	38.7 hPa (29 mm Hg)
· Density at 20°C (68°F):	1 g/cm ³
· Solubility in / Miscibility with	
Water:	Not miscible or difficult to mix.
· Viscosity:	
Dynamic at 20°C (68°F):	1000 mPas

10 Stability and reactivity

- **Thermal decomposition / conditions to be avoided:** Keep away from heat and direct sunlight. No decomposition if used according to specifications.
- Materials to be avoided: Reacts with peroxides and other radical forming substances.
- · Dangerous reactions: Exothermic polymerization.
- Dangerous products of decomposition:
- Carbon monoxide and carbon dioxide
- Hydrogen chloride (HCl)
- Possible in traces.
- · Additional information: Do not allow to enter sewers/ surface or ground water.

11 Toxicological information

- · Acute toxicity:
- Primary irritant effect:
- \cdot on the skin: Irritant to skin and mucous membranes.
- · on the eye: No irritating effect.
- · Sensitization: Sensitization possible through skin contact.

(Contd. on page 5)

⁻ USA ·

(Contd. of page 4)

Material Safety Data Sheet acc. to ISO/DIS 11014

Printing date 06/14/2013

Reviewed on 06/14/2013

Trade name: SILIKAL RV 368

• Additional toxicological information:

The product shows the following dangers according to internally approved calculation methods for preparations:

Irritant

12 Ecological information

· Additional ecological information:

· General notes:

Water hazard class 1 (Self-assessment): slightly hazardous for water

Do not allow undiluted product or large quantities of it to reach ground water, water course or sewage system.

13 Disposal considerations

· Product:

· Recommendation:

Must not be disposed of together with household garbage. Do not allow product to reach sewage system.

Must be specially treated adhering to official regulations.

· Uncleaned packagings:

Recommendation:

Packaging can be reused or recycled after cleaning.

Packagings that cannot be cleansed are to be disposed of in the same manner as the product.

Disposal must be made according to official regulations.

· Recommended cleansing agent: Acetone, ethylacetate

 DOT regulations: 		
	2	
· Hazard class:	3	
· Identification number:	UN1866	
Packing group:		
Proper shipping name (technica	, .	
Label	3	
· Land transport ADR/RID (cross	-border):	
(
e		
	2 Elommoble liquide	
ADR/RID class:	3 Flammable liquids	
Danger code (Kemler):	33	

Printing date 06/14/2013

Reviewed on 06/14/2013

Trade name: SILIKAL RV 368

		(Contd. of page
· Description of goods:	1866 RESIN SOLUTION	
· Maritime transport IMDG:		
~		
~		
· IMDG Class:	3	
· UN Number:	1866	
	3	
 Packaging group: EMS Number: 		
· EMS NUMBER: · Marine pollutant:	F-E,S-E No	
• Propper shipping name:	RESIN SOLUTION	
· Air transport ICAO-TI and IATA-D	IGR:	
\mathbf{A}		
ICAO/IATA Class:	3	
· UN/ID Number:	1866	
	3	
· Packaging group:	II	
Propper shipping name:	RESIN SOLUTION	
Regulations		
Sara	s substances):	
	s substances):	
• Sara • Section 355 (extremely hazardou None of the ingredient is listed.		
• Sara • Section 355 (extremely hazardou None of the ingredient is listed. • Section 313 (Specific toxic chem		
Sara Section 355 (extremely hazardou None of the ingredient is listed. Section 313 (Specific toxic chem 80-62-6 methyl methacrylate	ical listings):	
• Sara • Section 355 (extremely hazardou None of the ingredient is listed. • Section 313 (Specific toxic chem	ical listings):	
None of the ingredient is listed. • Section 313 (Specific toxic chemics) 80-62-6 methyl methacrylate • TSCA (Toxic Substances Control	ical listings):	
Sara Section 355 (extremely hazardou None of the ingredient is listed. Section 313 (Specific toxic chem 80-62-6 methyl methacrylate TSCA (Toxic Substances Control All ingredients are listed.	ical listings):	
Sara Section 355 (extremely hazardou None of the ingredient is listed. Section 313 (Specific toxic chemi 80-62-6 methyl methacrylate TSCA (Toxic Substances Control All ingredients are listed. Proposition 65	ical listings):	
Sara Section 355 (extremely hazardou None of the ingredient is listed. Section 313 (Specific toxic chem 80-62-6 methyl methacrylate TSCA (Toxic Substances Control All ingredients are listed. Proposition 65 Chemicals known to cause cance	ical listings): I Act): er:	
Sara Section 355 (extremely hazardou None of the ingredient is listed. Section 313 (Specific toxic chem 80-62-6 methyl methacrylate TSCA (Toxic Substances Control All ingredients are listed. Proposition 65 Chemicals known to cause cance None of the ingredients is listed.	ical listings): I Act): er:	
Sara Section 355 (extremely hazardou None of the ingredient is listed. Section 313 (Specific toxic chem 80-62-6 methyl methacrylate TSCA (Toxic Substances Control All ingredients are listed. Proposition 65 Chemicals known to cause cance None of the ingredients is listed. Chemicals known to cause repro	ical listings): I Act): er: er: ductive toxicity for females:	
Sara Section 355 (extremely hazardou None of the ingredient is listed. Section 313 (Specific toxic chem 80-62-6 methyl methacrylate TSCA (Toxic Substances Control All ingredients are listed. Proposition 65 Chemicals known to cause cance None of the ingredients is listed. Chemicals known to cause repro None of the ingredients is listed.	ical listings): I Act): er: er: ductive toxicity for females:	
 Sara Section 355 (extremely hazardou None of the ingredient is listed. Section 313 (Specific toxic chem 80-62-6 methyl methacrylate TSCA (Toxic Substances Control All ingredients are listed. Proposition 65 Chemicals known to cause cance None of the ingredients is listed. Chemicals known to cause repro None of the ingredients is listed. Chemicals known to cause repro None of the ingredients is listed. 	ical listings): I Act): er: eductive toxicity for females: eductive toxicity for males:	
 Sara Section 355 (extremely hazardou None of the ingredient is listed. Section 313 (Specific toxic chem 80-62-6 methyl methacrylate TSCA (Toxic Substances Control All ingredients are listed. Proposition 65 Chemicals known to cause cance None of the ingredients is listed. Chemicals known to cause repro None of the ingredients is listed. Chemicals known to cause repro None of the ingredients is listed. Chemicals known to cause repro None of the ingredients is listed. 	ical listings): I Act): er: eductive toxicity for females: eductive toxicity for males:	

· EPA (Environmental Protection Agency)

80-62-6 methyl methacrylate

· IARC (International Agency for Research on Cancer)

80-62-6 methyl methacrylate

103-11-7 2-ethylhexyl acrylate

(Contd. on page 7)

NL

3

3

USA

USA

Material Safety Data Sheet acc. to ISO/DIS 11014

Printing date 06/14/2013

Reviewed on 06/14/2013

Trade name: SILIKAL RV 368

	(Contd. of pa
•	ational Toxicology Program) f the ingredients is listed.
	hreshold Limit Value established by ACGIH)
•	meshold Limit value established by ACGIN
•	Serman Maximum Workplace Concentration)
	f the ingredients is listed.
	Ca (National Institute for Occupational Safety and Health)
	f the ingredients is listed.
	Ca (Occupational Safety & Health Administration)
None of	f the ingredients is listed.
· AGW (0	German Workplace Threshold Value)
	6 methyl methacrylate
103-11-	7 2-ethylhexyl acrylate
The pro	It related hazard informations: Iduct has been classified and marked in accordance with directives on hazardous materion symbols:
Xi Irritar	
methyl i	-determining components of labelling: methacrylate nexyl acrylate
37/38 Ir	nrases: lighly flammable. ritating to respiratory system and skin. lay cause sensitisation by skin contact.
3/7 9 16 33	 phrases: Keep container tightly closed in a cool place. Keep container in a well-ventilated place. Keep away from sources of ignition - No smoking. Take precautionary measures against static discharges. 9 Wear suitable protective clothing, gloves and eye/face protection.
	I labeling of certain preparations: s epoxy constituents. See information supplied by the manufacturer.
· Nationa	al regulations:
· Techni	cal instructions (air):
Class	Share in %

16 Other information

This information is based on our present knowledge. However, this shall not constitute a guarantee for any specific product features and shall not establish a legally valid contractual relationship.

· Department issuing MSDS: Silikal America

** Data compared to the previous version altered.